

IPD 2124-59
Cy 4 of 5
6 April 1959

TO : Chief, Materiel Branch, IPD-DD/P

SUBJECT: Elint Equipment Malfunction Report for March 1959

Detachment B - No equipment failures for March

Detachment C - [] System III & VI check out flight showed 400 cycle interference on tape. A low pass filter in the B plus return lead eliminated the trouble on Bench test. To be further tested on next flight.

25X1

[] Interference no longer present. Power supply fuse blew after 1.5 hours of flight due to loose circuit board power supply for [] "P" band interference consisting of aperiodic 65 millisecond bursts noted in flight which were not present in pre flight.

25X1

[] Again blew fuse in power supply to "L" and "P" band info amplifiers. No short found. Being investigated.

25X1
25X1

25X1

Detachment D - One recorder motor and take up gear box assembly failed on a System I recorder.

[]
Chief, Communications Section
IPD-DD/P

25X1

Distribution:

Orig & 1 - Addressee

- 3 - O-15
- 4 - RI
- 5 - Chrono

WWB/ba

SECRET